



- Plate mounting holes
- YAW-motor mounting holes

The holes must be between 3.5 and 4 mm

Do this job as precise as possible !!

2mm 3K carbon plate